

Amendments to the Specification

Please replace the paragraph located on page 14, lines 21-22 of the specification with the following replacement paragraph:

Figure[[s]] 29[[a-29g]] shows [[are]] lateral cross sections of a workpiece illustrating typical cross sectional defects as found on rough workpieces feeding a planer.

Please replace the paragraph located on page 45, lines 3-5 of the specification with the following replacement paragraph:

Figure[[s]] ~~29a through 29g~~ shows examples of typical cross-sectional geometric profile defects found in workpieces being fed into a planer. In reality workpieces fed to a planer will typically have a combination of these defects.